

LIST OF ANCILLARY FIGURE CAPTIONS

Figure A1 – a) View of the gravity base of stone masonry. b) An intermediate stage of the construction with the reservoir already filled. c) The final appearance of the dam.

Figure A2 – Plan and elevation views of the Gleno dam (modified from ANIDEL 1953).

Figure A3 – Pictures showing the destruction caused by the dam-break wave at Bueggio (a), Dezzo (b), Mazzunno powerhouse (c) and Corna di Darfo (d).

Figure A4 – A typical stretch of the Dezzo river.

Figure A5 – The remnants of the Angolo bridge overflowed by the dam-break wave.